


Parts needed to assemble and mount the W1 fastener set




Tools needed for mounting:

- drill
- pliers
- allen wrench

NOTE! A list of products corresponding with the selected accessories is available at www.klusdesign.eu/uk.






www.klusdesign.eu/uk




7. Drill a hole with a diameter of 5 mm in the selected extrusion.








9. Mount the plastic bolt (A), on the top put the plastic base (B), small power connector (C) and conductive head (D).



10. Run the cable from the LED strip to the small power connector. The cable can be led out through a hole drilled in an end cap or the extrusion.



11. Insert the arm (E) into the mounting bracket of the head. Block the arm by tightening the pressure screw in the head with the Allen wrench.



12. Attach the light fixture with the arm (E) to the top head (F). Block the rod by tightening the pressure screw in the top head with the Allen wrench.

